

IN THE SPECIFICATION:

Page 3, please amend paragraph [0007] as follows:

[0007] If two different inks are printed on two webs located next to each other, it may happen that the damping agent distributors 12 moving to and fro by an oscillator 14 mix the different inks used in two webs running next to each other, which leads to unsatisfactory printing results.